

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY CMI INTOXILYZER 5000 MAINTENANCE REPORT

RECEIVED DHSS Breath Alcohol Program
By Carol Day at 12:22 pm, Mar 09, 2010

ABICEL .			
Complete this report in duplicate at the time of the regular monthly preve instrument is repaired. Send copy to Department of Health; Retain original in de	epartment file.		
INTOXILYZER 5000 SN	DATE OF INSPECTION		
6600 4937	03/05//0 TIME OF INSPECTION		
LOCATION OF INSTRUMENT (STREET AND CITY)			
1200 E Linwood, Kansas City, Mo CHECKLIST	1800		
Place a check (✓) to left of each item if found to be satisfactory or if operating values where determined.) Unchecked items must be corrected before using in	vithin established limits. (Write in observed strument.		
DVM TEST: (.350 +/150)			
DIAGNOSTIC CHECK (PRINTOUT ATTACHED) Passed			
CHARACTER DISPLAY TEST PASSID			
PRINT TEST (PRINTOUT ATTACHED) PASSOC			
TX TIME AND DATE Passed			
Run three tests using a standard solution. All three tests must be within +/- 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (USE CAL. CHECK MODE) (PRINTOUT ATTACHED) 0.100% STANDARD - MUST READ BETWEEN 0.095% AND 0.105% INCLUSIVE 0.040% STANDARD - MUST READ BETWEEN 0.038% AND 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)			
TEST 1	TEST 3 /0.2		
IX SIMULATOR TEMPERATURE (34° +/- 2°C) 34,0 Degrees Ce	Isius Passed		
PERFORM RFI TEST (PRINTOUT ATTACHED) Passed			
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF SUBJECT BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)			
() 2 2 12 11 2	.1519 4 Over .19 .3		
REFUSALS 6 004 2 0.0509 () 1.1014 2 1.1519 / Over.19 3 List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary).			
Breath instrument tested and certified	within Missouri		
Department of Health guidelines.			
Buth Laboratories Inc., Lot#9270, FXP	ires 09/23/10,.10 Solution		
INSPECTING OFFICER	PRINT NAME		
P.O. DALIM MIMO, 4898	Dawn Minor		
TYPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER		
MO 580-1355 (9-94) AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER	816-482-8142 LAB-64		



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 09270 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1207 percent (w/vol) ethyl alcohol. The expiration date for this lot number is September 23, 2010 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.10 percent BAC.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC. HEV. DEFORTOMENHOPORSTUUMXYZ0123
ABCDEFGHOMENHOPORSTUUMXYZ0123456769
ABCDEFGHOMENHOPORSTUUMXYZ0123456769
ABCDEFGHOMENHOPORSTUUMYZ012345676913M*sbcde
ABCDEFGHOMENHOPORSTUUMXYZ012345676913#*sbcde

SH 66-004937 EZSS, 23 INUALID TEST IMHIBITED - RFI

1206 E LINWOOD KANSAS CITY MO INTOXILYZER - ALCOHOL AMALYZER NO MODEL 5000 SN 66-004937 83/03/2010

TEST	%86C	TIME
ATR ELAHK	. ଓଡ଼ିଶ	18:17
CAL. CHECK	. 161	13:13
AIR BLANK	<u>้ ย์ตี้ต์</u>	18:18
CAL, CHECK	. 101	18:18
ATR BLANK	. ้ ยี้ยี้ยี้	18: 19
CAL CHECK	. 162	18:19
	. ดัดิติ	18:20
ATK BLAHK	* 47675	400 20

HU REI PRESENT

1200 E LIHWOOD KAHSAS CITY HO-INTOXILYZER - ALCOHOL AMALYZER MO MODEL 5000 SN 66-004937 03/05/2010

DIAGNOSTIC. YEST

18:16

PROM CHECK	E735; 23	-, -	PASSED
RAM CHECK	1 .	11.	PASSED
TEMP CHECK	<i>\$</i> .	700	PASSED
PROCESSOR C			
SYNC PULS		1.	PASSED
SYNC SPEE		4.7	PASSED
MEG STABI	LITY		RASSED
POS STABI	LITY	ξ.	PASSED
REF RANGE	2		PASSED

DIAGNOSTIC

PASSED

PRINTER CHECK ASCDEFGHIJKLMNOPORSTUVWXYZ 0123456789

LOCATION OF TEST

OFFICER'S SIGNATURE & SERIAL NO. Form 123 P.D. (8-91)

SUBJECT NAME

LOCATION OF TEST

OFFICER'S SIGNATURE & SERIAL NO. Form 123 P.D. (8-91)

State of Missouri **DEPARTMENT OF HEALTH**



PERMIT TYPE II



Lab. 4 (R7-88)

DAWN MINOR

is hereby authorized to instruct and supervise operators, train instructors, inspect calibrate, perform field repairs, and operate the following breath analyzer(s):			
INTOXILYZER 5000			
air. Issued under the provisions of se	content of blood from a sample of expired (alveolar) octions 577.020 through 577.041, RSMo 1986. John & Wathunson		
Date 02/18/09 Number 920030 Expires	Director of State Public Health Laboratory Margart T. Danvelly		
MO 580-0771 (7-88)	- Director, Department of Health		